Comparison between versions† rev 4

	Version A	Version B	Version C	Version D	Version E	Version F	Version D1	Version E1	Version F1
Discrepancy	Not applicable to southern part of HK Island	Can be used all over HK.							
	It follows the incorrect time of the station even though it is not correct	Won't be wrong if one station is incorrect, when there are some other stations sending the right time.							
	╱	╱	There is a chance to have some seconds, or even some minutes off when time signal is not recived.	Fixed. -					
	╱	╱	╱	There is 1 component needed to be soldered	Fixed.				

				manually	
					Changed the MCU version.　(No software change)
					PSN changed: For Commercial Radio and Metro Radio stations, due to the format of their PSN (program service name) in the RDS data were changed: " CR 1 " -> "CR1　" " CR 2 " -> "CR2　" " M INFO " -> "M INFO " So the PSN in the firmware was modified accordingly. But the logic part of the firmware is not changed. The version numbers are changed from Version D to version D1, Version E to version E1, Version F to version F1, (D1 and E1 share the same firmware.)
Tolerance @25℃	<3 sec		<2 sec		<1 sec
New	／	／	Manual Adjust mode added		

features	/	/	/	Power saving mode added, making battery life > 1 yr. possible.
Sensitivity			Increased cover area	The receiving area is increased to cover the FuTian district in ShenZhen.
Battery life ※	9 months		7 months	8 months

※ Due to more retry when the station is weak, more power is consumed, the battery life will be shorter.

† Version number is at the end of the model number, e.g. HT14BK6E is 14", Black , the 6th model, **version E**.